

Hazardous Material Survey Report

March 1, 2024



Site

1233 Hodgekiss Street
Pittsburgh, PA

Prepared for:

Fukui Architects and
The HACP



Environmental, Inc.

37 West Main Street
Carnegie PA 15106
412-680-3132
412-278-5404 Fax
cbove@aaglo.com

Introduction

On January 28, 2024, a survey for Asbestos Containing Materials (ACM) and Lead Based Paint was performed for the HACP and Fukui Architects at 1233 Hodgekiss Street. This survey was performed to identify and quantify any asbestos containing materials which will require abatement prior to renovations. The survey was executed by Charles Bove, PA DOLI Building Inspector license number 048871, of Allegheny Global Environmental Inc. (AGE).

Facility Description

The facility is an unoccupied single family residence

Survey Procedures

All sampling was conducted as a pre-renovation survey.

Analytical Procedures

The collected SACM sample was analyzed using Polarized Light Microscopy (PLM) in conjunction with dispersion staining techniques using EPA Method 600/R-93/116. The bulk laboratory analysis provides the asbestos content (positive or negative), percentage of asbestos, asbestos type and identification of other non-asbestos fibers. The samples were analyzed by AGE. Lead was tested via x-ray fluoroscope.

Survey Results

Asbestos:

Basement – Boiler – Approx 200 sq ft of boiler insulation – Friable

Lead Based Paint:

All painted surfaces with the exception of the stair railing are painted with lead based paint.



Recommendations

It is recommended that the boiler be removed and that lead paint be abated or encapsulated. Prior to abatement of the boiler, it is required to notify the Allegheny County Health Department.

Limitations/Qualifications

To the extent practicable, intrusive sampling was performed to ascertain the presence of obscured potential ACM however, undetected ACM may exist in areas inside walls, above inaccessible ceilings, below multiple layers of flooring, etc., which could not be accessed for inspection. This report summarizes AGE's evaluation of the conditions observed at the subject facility at the time of the survey. Our findings are based upon our observations and analysis of the samples obtained at the time of the survey. Any conditions discovered which deviate from the data contained in this report should be presented to us for our evaluation. The findings contained herein have been prepared in general accordance with all Federal, State, and Local regulations, as well as accepted professional practices as applied by similar professionals in the community at the time of its preparation.

Should you have any questions regarding the above presented information or if we may be of further assistance, please call me at (412) 680-3132.

Sincerely,



Charlie Bove, PA DOLI 048871



Analytical Results



PLM Bulk Asbestos Laboratory Report

Client:	Fukui Architects	Job Number:	
Project:	1233 Hodgkiss Street	Date Received:	January 29, 2024
	P.O.	Date Analyzed:	January 29, 2024

Lab I.D.	Client I.D.	Client Location/Information	Analyst Description	Other Materials Present - Type and Percent	Asbestos Type and Percent	Asbestos Present
012966	01	Walls/Ceilings	White Plaster Skim Coat	Gypsum, Opaques, Others 100%	ND	No
012967	01A	Walls/Ceilings	Grey Plaster Base Coat	Cellulose, Quartz, Gypsum, Opaques, Others 100%	ND	No
012968	02	Walls/Ceilings	White Plaster Skim Coat	Gypsum, Opaques, Others 100%	ND	No
012969	02A	Walls/Ceilings	Grey Plaster Base Coat	Cellulose, Quartz, Gypsum, Opaques, Others 100%	ND	No
012970	03	Walls/Ceilings	White Plaster Skim Coat	Gypsum, Opaques, Others 100%	ND	No
012971	03A	Walls/Ceilings	Grey Plaster Base Coat	Cellulose, Quartz, Gypsum, Opaques, Others 100%	ND	No
012972	04	Walls/Ceilings	White Plaster Skim Coat	Gypsum, Opaques, Others 100%	ND	No
012973	04A	Walls/Ceilings	Grey Plaster Base Coat	Cellulose, Quartz, Gypsum, Opaques, Others 100%	ND	No
012974	05	Walls/Ceilings	White Plaster Skim Coat	Gypsum, Opaques, Others 100%	ND	No
012975	05A	Walls/Ceilings	Grey Plaster Base Coat	Cellulose, Quartz, Gypsum, Opaques, Others 100%	ND	No
012976	06	Kitchen	White/Grey Stripe Floor Tile	Non-fibrous 100%	ND	No
012977	06A	Kitchen	Brown Mastic	Cellulose, Others 100%	ND	No
012978	07	Kitchen	White/Grey Stripe Floor Tile	Non-fibrous 100%	ND	No
012979	07A	Kitchen	Brown Mastic	Cellulose, Others 100%	ND	No
012980	08	Foyer	Red Floor Tile	Opaques, Others 100%	ND	No
012981	08A	Foyer	Tan Mastic	Cellulose, Others 100%	ND	No
012982	09	Foyer	Red Floor Tile	Opaques, Others 100%	ND	No
012983	09A	Foyer	Tan Mastic	Cellulose, Others 100%	ND	No
012984	10	Boiler	Light Grey Insulation	Cellulose, Opaques, Others 50%	Chrysotile 50%	Yes

Analyzed By: Mark Shatlock

Signature: *Mark F. Shatlock*

Reviewed By: Diana Clayton

Samples are analyzed according to the U.S. EPA "Method for the Determination of Asbestos in Bulk Insulation Samples: EPA 600/R-93-116). Bulk sample report relates to only those items tested. All samples are retained for 30 days. Tile, Vinyl, Foam, Plastic and Fine Powder samples may contain Asbestos fibers of such small diameter that these fibers may not be detected by PLM. Such samples should be analyzed by XRD, TEM or SEM for greater certainty of Asbestos content. *ND = no asbestos detected; Detection Limit <1 %, Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1 %; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed/positive stop; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. ND or Trace results by PLM are inconclusive. PLM report relates ONLY to the items tested. NVLAP 901003

1233 Hodgekiss Street

XRF Data

Calibrate 10 10 10 (Standard - 10)								
Data Point	Date	Site Code	Bldg	Room	Homogenous Area	Color	Substrate	Lead Content in mg/cm ²
1	1/29/2024	Cal	*	*	*	*	*	Pass
2	1/29/2024	Cal	*	*	*	*	*	Pass
3	1/29/2024	Cal	*	*	*	*	*	Pass
4	1/29/2024	1233	Res	Living	Wall 1	White	Plaster	3.9
5	1/29/2024	1233	Res	Living	Wall 2	White	Plaster	4.2
6	1/29/2024	1233	Res	Living	Wall 3	White	Plaster	4.2
7	1/29/2024	1233	Res	Living	Wall 4	White	Plaster	4.5
8	1/29/2024	1233	Res	Living	Ceiling	White	Plaster	4.2
9	1/29/2024	1233	Res	Dining	Wall 1	White	Plaster	3.9
10	1/29/2024	1233	Res	Dining	Wall 2	White	Plaster	4.2
11	1/29/2024	1233	Res	Dining	Wall 3	White	Plaster	3.9
12	1/29/2024	1233	Res	Dining	Wall 4	White	Plaster	4.2
13	1/29/2024	1233	Res	Dining	Ceiling	White	Plaster	4.5
14	1/29/2024	1233	Res	Kitchen	Wall 1	White	Plaster	4.0
15	1/29/2024	1233	Res	Kitchen	Wall 2	White	Plaster	3.5
16	1/29/2024	1233	Res	Kitchen	Wall 3	White	Plaster	4.4
17	1/29/2024	1233	Res	Kitchen	Wall 4	White	Plaster	3.9
18	1/29/2024	1233	Res	Kitchen	Ceiling	White	Plaster	4.2
19	1/29/2024	1233	Res	Bed 1	Wall 1	White	Plaster	4.5
20	1/29/2024	1233	Res	Bed 1	Wall 2	White	Plaster	4.4
21	1/29/2024	1233	Res	Bed 1	Wall 3	White	Plaster	3.9
22	1/29/2024	1233	Res	Bed 1	Wall 4	White	Plaster	4.2
23	1/29/2024	1233	Res	Bed 1	Ceiling	White	Plaster	4.4
24	1/29/2024	1233	Res	Bed 2	Wall 1	White	Plaster	3.9
25	1/29/2024	1233	Res	Bed 2	Wall 2	White	Plaster	4.2
26	1/29/2024	1233	Res	Bed 2	Wall 3	White	Plaster	4.5
27	1/29/2024	1233	Res	Bed 2	Wall 4	White	Plaster	3.3
28	1/29/2024	1233	Res	Bed 2	Ceiling	White	Plaster	4.2
29	1/29/2024	1233	Res	Bed 3	Wall 1	White	Plaster	3.9
30	1/29/2024	1233	Res	Bed 3	Wall 2	White	Plaster	4.0
31	1/29/2024	1233	Res	Bed 3	Wall 3	White	Plaster	3.2
32	1/29/2024	1233	Res	Bed 3	Wall 4	White	Plaster	3.5
33	1/29/2024	1233	Res	Bed 3	Ceiling	White	Plaster	3.8
34	1/29/2024	1233	Res	Attic	Wall 1	White	Plaster	4.6
35	1/29/2024	1233	Res	Attic	Wall 2	White	Plaster	4.2
36	1/29/2024	1233	Res	Attic	Wall 3	White	Plaster	4.4
37	1/29/2024	1233	Res	Attic	Wall 4	White	Plaster	3.9
38	1/29/2024	1233	Res	Attic	Ceiling	White	Plaster	4.8
39	1/29/2024	1233	Res	Hall	Wall	White	Plaster	4.4
40	1/29/2024	1233	Res	Hall	Wall	White	Plaster	3.9
41	1/29/2024	1233	Res	Railing	Railing	Wood	Wood	0.0

42	1/29/2024	1233	Res	Railing	Railing	Wood	Wood	0.0
43	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	3.3
44	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	4.2
45	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	3.9
46	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	4.0
47	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	3.2
48	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	3.5
49	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	3.8
50	1/29/2024	1233	Res	Windows	Windows	Wood	Wood	4.6
51	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.2
52	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	3.2
53	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	3.5
54	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	3.8
55	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.6
56	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.2
57	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.4
58	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	3.9
59	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.8
60	1/29/2024	1233	Res	Trim	Trim	Wood	Wood	4.4

Hazardous Material Survey Report

March 1, 2024



Site

447-449 and 453-455 Sweetbriar Street
Pittsburgh, PA

Prepared for:

Fukui Architects and
The HACP



Environmental, Inc.

37 West Main Street
Carnegie PA 15106
412-680-3132
412-278-5404 Fax
cbove@aaglo.com

Introduction

On January 28, 2024, a survey for Asbestos Containing Materials (ACM) and Lead Based Paint was performed for the HACP and Fukui Architects at 447-449 and 453-455 Sweetbriar Street. This survey was performed to identify and quantify any asbestos containing materials which will require abatement prior to renovations. The survey was executed by Charles Bove, PA DOLI Building Inspector license number 048871, of Allegheny Global Environmental Inc. (AGE).

Facility Description

The site is comprised of two identical duplexes with integral garages and basement entries. Both structures have drywall interiors and fiberglass insulation.

Survey Procedures

All sampling was conducted as a pre-renovation survey.

Analytical Procedures

The collected SACM sample was analyzed using Polarized Light Microscopy (PLM) in conjunction with dispersion staining techniques using EPA Method 600/R-93/116. The bulk laboratory analysis provides the asbestos content (positive or negative), percentage of asbestos, asbestos type and identification of other non-asbestos fibers. The samples were analyzed by AGE. Lead was tested via x-ray fluoroscope.

Survey Results

Asbestos:

No Asbestos Present

Lead Based Paint:

No Lead Based Paint Present



Recommendations

Although no asbestos was found present in either building, the Allegheny County Health Department still requests notification accompanied by this report prior to renovations.

Limitations/Qualifications

To the extent practicable, intrusive sampling was performed to ascertain the presence of obscured potential ACM however, undetected ACM may exist in areas inside walls, above inaccessible ceilings, below multiple layers of flooring, etc., which could not be accessed for inspection. This report summarizes AGE's evaluation of the conditions observed at the subject facility at the time of the survey. Our findings are based upon our observations and analysis of the samples obtained at the time of the survey. Any conditions discovered which deviate from the data contained in this report should be presented to us for our evaluation. The findings contained herein have been prepared in general accordance with all Federal, State, and Local regulations, as well as accepted professional practices as applied by similar professionals in the community at the time of its preparation.

Should you have any questions regarding the above presented information or if we may be of further assistance, please call me at (412) 680-3132.

Sincerely,



Charlie Bove, PA DOLI 048871



Environmental, Inc.

Analytical Results

PLM Bulk Asbestos Laboratory Report

Client:	Fukui Architects and the HACP	
Project:	Sweetbriar Street	P.O.

Job Number:	CB-24-
Date Received:	January 29, 2024
Date Analyzed:	January 29, 2024

Lab I.D.	Client I.D.	Client Location/Information	Analyst Description	Other Materials Present - Type and Percent	Asbestos Type and Percent	Asbestos Present
012901	1	447	Beige Floor Tile	Opakes, Others 100%	ND	No
012902	1A	447	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012903	2	447	Beige Floor Tile	Opakes, Others 100%	ND	No
012904	2A	447	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012905	3	447	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012906	3A	447	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012907	4	447	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012908	4A	447	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012909	5	447	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012910	5A	447	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012911	6	447	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012912	7	447	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012913	8	447	Cove base	Rubber, Others 100%	ND	No
012914	8A	447	Adhesive	Cellulose, Binders, Others 100%	ND	No
012915	9	447	Cove base	Rubber, Others 100%	ND	No
012916	9A	447	Adhesive	Cellulose, Binders, Others 100%	ND	No
012917	10	449	Beige Floor Tile	Opakes, Others 100%	ND	No
012918	10A	449	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012919	11	449	Beige Floor Tile	Opakes, Others 100%	ND	No
012920	11A	449	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012921	12	449	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012922	12A	449	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012923	13	449	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012924	13A	449	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012925	14	449	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012926	14A	449	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012927	15	449	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012928	16	449	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012929	17	449	Cove base	Rubber, Others 100%	ND	No
012930	17A	449	Adhesive	Cellulose, Binders, Others 100%	ND	No

Analyzed By: Mark Shatlock

Signature: Mark F. Shatlock Reviewed By: Diana Clayton

Samples are analyzed according to the U.S. EPA "Method for the Determination of Asbestos in Bulk Insulation Samples: EPA 600/R-93-116). Bulk sample report relates to only those items tested. All samples are retained for 30 days. Tile, Vinyl, Foam, Plastic and Fine Powder samples may contain Asbestos fibers of such small diameter that these fibers may not be detected by PLM. Such samples should be analyzed by XRD, TEM or SEM for greater certainty of Asbestos content. *ND = no asbestos detected; Detection Limit <1 %, Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1 %; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed/positive stop; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. ND or Trace results by PLM are inconclusive. PLM report relates ONLY to the items tested. NVLAP 901003



PLM Bulk Asbestos Laboratory Report

Client:	Fukui Architects and the HACP	
Project:	Sweetbriar Street	P.O.

Job Number:	CB-24-
Date Received:	January 29, 2024
Date Analyzed:	January 29, 2024

Lab I.D.	Client I.D.	Client Location/Information	Analyst Description	Other Materials Present - Type and Percent	Asbestos Type and Percent	Asbestos Present
012931	18	453	Beige Floor Tile	Opakes, Others 100%	ND	No
012932	18A	453	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012933	19	453	Beige Floor Tile	Opakes, Others 100%	ND	No
012934	19A	453	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012935	20	453	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012936	20A	453	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012937	21	453	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012938	21A	453	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012939	22	453	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012940	22A	453	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012941	23	453	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012942	24	453	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012943	25	453	Cove base	Rubber, Others 100%	ND	No
012944	25A	453	Adhesive	Cellulose, Binders, Others 100%	ND	No
012945	26	455	Beige Floor Tile	Opakes, Others 100%	ND	No
012946	26A	455	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012927	27	455	Beige Floor Tile	Opakes, Others 100%	ND	No
012928	27A	455	Yellow/Tan Mastic	Cellulose, Others 100%	ND	No
012929	28	455	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012930	28A	455	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012931	29	455	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012932	29A	455	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012933	30	455	Drywall	Paint, Cellulose, Gypsum, Others 100%	ND	No
012934	30A	455	Joint Compound	Paint, Gypsum, Others 100%	ND	No
012935	31	455	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012936	32	455	Fiberglass Insulation	Fiberglass, Others 100%	ND	No
012937	33	455	Cove base	Rubber, Others 100%	ND	No
012938	33A	455	Adhesive	Cellulose, Binders, Others 100%	ND	No

Analyzed By: _____ Mark Shatlock

Signature: *Mark F. Shatlock* Reviewed By: _____ Diana Clayton

Samples are analyzed according to the U.S. EPA "Method for the Determination of Asbestos in Bulk Insulation Samples: EPA 600/R-93-116). Bulk sample report relates to only those items tested. All samples are retained for 30 days. Tile, Vinyl, Foam, Plastic and Fine Powder samples may contain Asbestos fibers of such small diameter that these fibers may not be detected by PLM. Such samples should be analyzed by XRD, TEM or SEM for greater certainty of Asbestos content. *ND = no asbestos detected; Detection Limit <1 %, Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1 %; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed/positive stop; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. ND or Trace results by PLM are inconclusive. PLM report relates ONLY to the items tested. NVLAP 901003

Sweetbriar Street

XRF Data

Calibrate 10 10 10 (Standard - 10)								
Data Point	Date	Site Code	Bldg	Room	Homogenous Area	Color	Substrate	Lead Content in mg/cm ²
1	1/29/2024	Cal	*	*	*	*	*	Pass
2	1/29/2024	Cal	*	*	*	*	*	Pass
3	1/29/2024	Cal	*	*	*	*	*	Pass
4	1/29/2024	447	Res	Living	Wall 1	White	Drywall	0.0
5	1/29/2024	447	Res	Living	Wall 2	White	Plaster	0.0
6	1/29/2024	447	Res	Living	Wall 3	White	Plaster	0.0
7	1/29/2024	447	Res	Living	Wall 4	White	Plaster	0.0
8	1/29/2024	447	Res	Living	Ceiling	White	Plaster	0.0
9	1/29/2024	447	Res	Dining	Wall 1	White	Plaster	0.0
10	1/29/2024	447	Res	Dining	Wall 2	White	Plaster	0.0
11	1/29/2024	447	Res	Dining	Wall 3	White	Plaster	0.0
12	1/29/2024	447	Res	Dining	Wall 4	White	Plaster	0.0
13	1/29/2024	447	Res	Dining	Ceiling	White	Plaster	0.0
14	1/29/2024	447	Res	Kitchen	Wall 1	White	Plaster	0.0
15	1/29/2024	447	Res	Kitchen	Wall 2	White	Plaster	0.0
16	1/29/2024	447	Res	Kitchen	Wall 3	White	Plaster	0.0
17	1/29/2024	447	Res	Kitchen	Wall 4	White	Plaster	0.0
18	1/29/2024	447	Res	Kitchen	Ceiling	White	Plaster	0.0
19	1/29/2024	447	Res	Bed 1	Wall 1	White	Plaster	0.0
20	1/29/2024	447	Res	Bed 1	Wall 2	White	Plaster	0.0
21	1/29/2024	447	Res	Bed 1	Wall 3	White	Plaster	0.0
22	1/29/2024	447	Res	Bed 1	Wall 4	White	Plaster	0.0
23	1/29/2024	447	Res	Bed 1	Ceiling	White	Plaster	0.0
24	1/29/2024	447	Res	Bed 2	Wall 1	White	Plaster	0.0
25	1/29/2024	447	Res	Bed 2	Wall 2	White	Plaster	0.0
26	1/29/2024	447	Res	Bed 2	Wall 3	White	Plaster	0.0
27	1/29/2024	447	Res	Bed 2	Wall 4	White	Plaster	0.0
28	1/29/2024	447	Res	Bed 2	Ceiling	White	Plaster	0.0
29	1/29/2024	447	Res	Bed 3	Wall 1	White	Plaster	0.0
30	1/29/2024	447	Res	Bed 3	Wall 2	White	Plaster	0.0
31	1/29/2024	447	Res	Bed 3	Wall 3	White	Plaster	0.0
32	1/29/2024	447	Res	Bed 3	Wall 4	White	Plaster	0.0
33	1/29/2024	447	Res	Bed 3	Ceiling	White	Plaster	0.0
34	1/29/2024	447	Res	Attic	Wall 1	White	Plaster	0.0
35	1/29/2024	447	Res	Attic	Wall 2	White	Plaster	0.0
36	1/29/2024	447	Res	Attic	Wall 3	White	Plaster	0.0
37	1/29/2024	447	Res	Attic	Wall 4	White	Plaster	0.0
38	1/29/2024	447	Res	Attic	Ceiling	White	Plaster	0.0
39	1/29/2024	447	Res	Hall	Wall	White	Plaster	0.0
40	1/29/2024	447	Res	Hall	Wall	White	Plaster	0.0
41	1/29/2024	447	Res	Railing	Railing	Wood	Wood	0.0

42	1/29/2024	447	Res	Railing	Railing	Wood	Wood	0.0
43	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
44	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
45	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
46	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
47	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
48	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
49	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
50	1/29/2024	447	Res	Windows	Windows	Wood	Wood	0.0
51	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
52	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
53	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
54	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
55	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
56	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
57	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
58	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
59	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0
60	1/29/2024	447	Res	Trim	Trim	Wood	Wood	0.0

Sweetbriar Street

XRF Data

Calibrate 10 10 10 (Standard - 10)								
Data Point	Date	Site Code	Bldg	Room	Homogenous Area	Color	Substrate	Lead Content in mg/cm ²
1	1/29/2024	Cal	*	*	*	*	*	Pass
2	1/29/2024	Cal	*	*	*	*	*	Pass
3	1/29/2024	Cal	*	*	*	*	*	Pass
4	1/29/2024	449	Res	Living	Wall 1	White	Drywall	0.0
5	1/29/2024	449	Res	Living	Wall 2	White	Plaster	0.0
6	1/29/2024	449	Res	Living	Wall 3	White	Plaster	0.0
7	1/29/2024	449	Res	Living	Wall 4	White	Plaster	0.0
8	1/29/2024	449	Res	Living	Ceiling	White	Plaster	0.0
9	1/29/2024	449	Res	Dining	Wall 1	White	Plaster	0.0
10	1/29/2024	449	Res	Dining	Wall 2	White	Plaster	0.0
11	1/29/2024	449	Res	Dining	Wall 3	White	Plaster	0.0
12	1/29/2024	449	Res	Dining	Wall 4	White	Plaster	0.0
13	1/29/2024	449	Res	Dining	Ceiling	White	Plaster	0.0
14	1/29/2024	449	Res	Kitchen	Wall 1	White	Plaster	0.0
15	1/29/2024	449	Res	Kitchen	Wall 2	White	Plaster	0.0
16	1/29/2024	449	Res	Kitchen	Wall 3	White	Plaster	0.0
17	1/29/2024	449	Res	Kitchen	Wall 4	White	Plaster	0.0
18	1/29/2024	449	Res	Kitchen	Ceiling	White	Plaster	0.0
19	1/29/2024	449	Res	Bed 1	Wall 1	White	Plaster	0.0
20	1/29/2024	449	Res	Bed 1	Wall 2	White	Plaster	0.0
21	1/29/2024	449	Res	Bed 1	Wall 3	White	Plaster	0.0
22	1/29/2024	449	Res	Bed 1	Wall 4	White	Plaster	0.0
23	1/29/2024	449	Res	Bed 1	Ceiling	White	Plaster	0.0
24	1/29/2024	449	Res	Bed 2	Wall 1	White	Plaster	0.0
25	1/29/2024	449	Res	Bed 2	Wall 2	White	Plaster	0.0
26	1/29/2024	449	Res	Bed 2	Wall 3	White	Plaster	0.0
27	1/29/2024	449	Res	Bed 2	Wall 4	White	Plaster	0.0
28	1/29/2024	449	Res	Bed 2	Ceiling	White	Plaster	0.0
29	1/29/2024	449	Res	Bed 3	Wall 1	White	Plaster	0.0
30	1/29/2024	449	Res	Bed 3	Wall 2	White	Plaster	0.0
31	1/29/2024	449	Res	Bed 3	Wall 3	White	Plaster	0.0
32	1/29/2024	449	Res	Bed 3	Wall 4	White	Plaster	0.0
33	1/29/2024	449	Res	Bed 3	Ceiling	White	Plaster	0.0
34	1/29/2024	449	Res	Attic	Wall 1	White	Plaster	0.0
35	1/29/2024	449	Res	Attic	Wall 2	White	Plaster	0.0
36	1/29/2024	449	Res	Attic	Wall 3	White	Plaster	0.0
37	1/29/2024	449	Res	Attic	Wall 4	White	Plaster	0.0
38	1/29/2024	449	Res	Attic	Ceiling	White	Plaster	0.0
39	1/29/2024	449	Res	Hall	Wall	White	Plaster	0.0
40	1/29/2024	449	Res	Hall	Wall	White	Plaster	0.0
41	1/29/2024	449	Res	Railing	Railing	Wood	Wood	0.0

42	1/29/2024	449	Res	Railing	Railing	Wood	Wood	0.0
43	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
44	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
45	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
46	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
47	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
48	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
49	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
50	1/29/2024	449	Res	Windows	Windows	Wood	Wood	0.0
51	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
52	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
53	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
54	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
55	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
56	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
57	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
58	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
59	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0
60	1/29/2024	449	Res	Trim	Trim	Wood	Wood	0.0

Sweetbriar Street

XRF Data

Calibrate 10 10 10 (Standard - 10)								
Data Point	Date	Site Code	Bldg	Room	Homogenous Area	Color	Substrate	Lead Content in mg/cm ²
1	1/29/2024	Cal	*	*	*	*	*	Pass
2	1/29/2024	Cal	*	*	*	*	*	Pass
3	1/29/2024	Cal	*	*	*	*	*	Pass
4	1/29/2024	453	Res	Living	Wall 1	White	Drywall	0.0
5	1/29/2024	453	Res	Living	Wall 2	White	Plaster	0.0
6	1/29/2024	453	Res	Living	Wall 3	White	Plaster	0.0
7	1/29/2024	453	Res	Living	Wall 4	White	Plaster	0.0
8	1/29/2024	453	Res	Living	Ceiling	White	Plaster	0.0
9	1/29/2024	453	Res	Dining	Wall 1	White	Plaster	0.0
10	1/29/2024	453	Res	Dining	Wall 2	White	Plaster	0.0
11	1/29/2024	453	Res	Dining	Wall 3	White	Plaster	0.0
12	1/29/2024	453	Res	Dining	Wall 4	White	Plaster	0.0
13	1/29/2024	453	Res	Dining	Ceiling	White	Plaster	0.0
14	1/29/2024	453	Res	Kitchen	Wall 1	White	Plaster	0.0
15	1/29/2024	453	Res	Kitchen	Wall 2	White	Plaster	0.0
16	1/29/2024	453	Res	Kitchen	Wall 3	White	Plaster	0.0
17	1/29/2024	453	Res	Kitchen	Wall 4	White	Plaster	0.0
18	1/29/2024	453	Res	Kitchen	Ceiling	White	Plaster	0.0
19	1/29/2024	453	Res	Bed 1	Wall 1	White	Plaster	0.0
20	1/29/2024	453	Res	Bed 1	Wall 2	White	Plaster	0.0
21	1/29/2024	453	Res	Bed 1	Wall 3	White	Plaster	0.0
22	1/29/2024	453	Res	Bed 1	Wall 4	White	Plaster	0.0
23	1/29/2024	453	Res	Bed 1	Ceiling	White	Plaster	0.0
24	1/29/2024	453	Res	Bed 2	Wall 1	White	Plaster	0.0
25	1/29/2024	453	Res	Bed 2	Wall 2	White	Plaster	0.0
26	1/29/2024	453	Res	Bed 2	Wall 3	White	Plaster	0.0
27	1/29/2024	453	Res	Bed 2	Wall 4	White	Plaster	0.0
28	1/29/2024	453	Res	Bed 2	Ceiling	White	Plaster	0.0
29	1/29/2024	453	Res	Bed 3	Wall 1	White	Plaster	0.0
30	1/29/2024	453	Res	Bed 3	Wall 2	White	Plaster	0.0
31	1/29/2024	453	Res	Bed 3	Wall 3	White	Plaster	0.0
32	1/29/2024	453	Res	Bed 3	Wall 4	White	Plaster	0.0
33	1/29/2024	453	Res	Bed 3	Ceiling	White	Plaster	0.0
34	1/29/2024	453	Res	Attic	Wall 1	White	Plaster	0.0
35	1/29/2024	453	Res	Attic	Wall 2	White	Plaster	0.0
36	1/29/2024	453	Res	Attic	Wall 3	White	Plaster	0.0
37	1/29/2024	453	Res	Attic	Wall 4	White	Plaster	0.0
38	1/29/2024	453	Res	Attic	Ceiling	White	Plaster	0.0
39	1/29/2024	453	Res	Hall	Wall	White	Plaster	0.0
40	1/29/2024	453	Res	Hall	Wall	White	Plaster	0.0
41	1/29/2024	453	Res	Railing	Railing	Wood	Wood	0.0

42	1/29/2024	453	Res	Railing	Railing	Wood	Wood	0.0
43	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
44	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
45	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
46	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
47	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
48	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
49	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
50	1/29/2024	453	Res	Windows	Windows	Wood	Wood	0.0
51	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
52	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
53	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
54	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
55	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
56	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
57	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
58	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
59	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0
60	1/29/2024	453	Res	Trim	Trim	Wood	Wood	0.0

Sweetbriar Street

XRF Data

Calibrate 10 10 10 (Standard - 10)								
Data Point	Date	Site Code	Bldg	Room	Homogenous Area	Color	Substrate	Lead Content in mg/cm ²
1	1/29/2024	Cal	*	*	*	*	*	Pass
2	1/29/2024	Cal	*	*	*	*	*	Pass
3	1/29/2024	Cal	*	*	*	*	*	Pass
4	1/29/2024	455	Res	Living	Wall 1	White	Drywall	0.0
5	1/29/2024	455	Res	Living	Wall 2	White	Plaster	0.0
6	1/29/2024	455	Res	Living	Wall 3	White	Plaster	0.0
7	1/29/2024	455	Res	Living	Wall 4	White	Plaster	0.0
8	1/29/2024	455	Res	Living	Ceiling	White	Plaster	0.0
9	1/29/2024	455	Res	Dining	Wall 1	White	Plaster	0.0
10	1/29/2024	455	Res	Dining	Wall 2	White	Plaster	0.0
11	1/29/2024	455	Res	Dining	Wall 3	White	Plaster	0.0
12	1/29/2024	455	Res	Dining	Wall 4	White	Plaster	0.0
13	1/29/2024	455	Res	Dining	Ceiling	White	Plaster	0.0
14	1/29/2024	455	Res	Kitchen	Wall 1	White	Plaster	0.0
15	1/29/2024	455	Res	Kitchen	Wall 2	White	Plaster	0.0
16	1/29/2024	455	Res	Kitchen	Wall 3	White	Plaster	0.0
17	1/29/2024	455	Res	Kitchen	Wall 4	White	Plaster	0.0
18	1/29/2024	455	Res	Kitchen	Ceiling	White	Plaster	0.0
19	1/29/2024	455	Res	Bed 1	Wall 1	White	Plaster	0.0
20	1/29/2024	455	Res	Bed 1	Wall 2	White	Plaster	0.0
21	1/29/2024	455	Res	Bed 1	Wall 3	White	Plaster	0.0
22	1/29/2024	455	Res	Bed 1	Wall 4	White	Plaster	0.0
23	1/29/2024	455	Res	Bed 1	Ceiling	White	Plaster	0.0
24	1/29/2024	455	Res	Bed 2	Wall 1	White	Plaster	0.0
25	1/29/2024	455	Res	Bed 2	Wall 2	White	Plaster	0.0
26	1/29/2024	455	Res	Bed 2	Wall 3	White	Plaster	0.0
27	1/29/2024	455	Res	Bed 2	Wall 4	White	Plaster	0.0
28	1/29/2024	455	Res	Bed 2	Ceiling	White	Plaster	0.0
29	1/29/2024	455	Res	Bed 3	Wall 1	White	Plaster	0.0
30	1/29/2024	455	Res	Bed 3	Wall 2	White	Plaster	0.0
31	1/29/2024	455	Res	Bed 3	Wall 3	White	Plaster	0.0
32	1/29/2024	455	Res	Bed 3	Wall 4	White	Plaster	0.0
33	1/29/2024	455	Res	Bed 3	Ceiling	White	Plaster	0.0
34	1/29/2024	455	Res	Attic	Wall 1	White	Plaster	0.0
35	1/29/2024	455	Res	Attic	Wall 2	White	Plaster	0.0
36	1/29/2024	455	Res	Attic	Wall 3	White	Plaster	0.0
37	1/29/2024	455	Res	Attic	Wall 4	White	Plaster	0.0
38	1/29/2024	455	Res	Attic	Ceiling	White	Plaster	0.0
39	1/29/2024	455	Res	Hall	Wall	White	Plaster	0.0
40	1/29/2024	455	Res	Hall	Wall	White	Plaster	0.0
41	1/29/2024	455	Res	Railing	Railing	Wood	Wood	0.0

42	1/29/2024	455	Res	Railing	Railing	Wood	Wood	0.0
43	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
44	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
45	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
46	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
47	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
48	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
49	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
50	1/29/2024	455	Res	Windows	Windows	Wood	Wood	0.0
51	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
52	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
53	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
54	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
55	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
56	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
57	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
58	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
59	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0
60	1/29/2024	455	Res	Trim	Trim	Wood	Wood	0.0