



Housing Authority of the City of Pittsburgh

Contracting Officer
100 Ross Street
2nd Floor Suite 200
Pittsburgh, PA 15219
(412) 456-5248
Fax: (412) 456-5007
www.hacp.org

April 15, 2015

Northview Heights Family High-Rise Balcony Structural Restoration RFP#600-04-15

ADDENDUM NO.2

This addendum, issued April 15, 2015, becomes in its entirety a part of the Invitation for Bid IFB #600-04-15 as is fully set forth herein:

Item 1: Q: Clarifications regarding Part 4, Technical Specifications.

A1: Revise Note N2 on sheet S1.0 as follows: LOCATION OF DELAMINATED CONCRETE WITHIN CONCRETE BEAM ENCASMENT. THE CONTRACTOR SHALL REMOVE ALL LOOSE CONCRETE AT LOCATION OF VISIBLE DAMAGE AND PROVIDE LOCALIZED REPAIR PER DETAIL ~~102/S1.1~~ 103/S1.1.


A2: Revise Concrete Repair General Notes, Demolition Note 6 located on sheet S2.0 as follows: ~~SAND-BLAST~~ CLEAN ALL DEMOLISHED SURFACES AND REINFORCING. REMOVE ALL LOOSE MATERIALS AND RUST AND DISPOSE ALL DEBRIS OFF SITE.

A3: Revise Specification Section 03 31 10 Concrete Demolition and Repair Paragraph 3.3.A. as follows: Surface Preparation: After the demolition is completed and the surface has been tested for soundness, the exposed steel shall be thoroughly cleaned ~~by sandblasting~~ and incorporated into new concrete patch. A 3000 psi water blast shall be used to clean the surface of dust and to wet the surface for application of repair materials. The prepared surface shall be free of all substances and contaminants that would inhibit a good bond.

A4: Due Date: The Bids Due Date remains the same on April 17, 2015. The time and location remain unchanged at 2:00 PM at the HACP Procurement Department, 100 Ross Street, 2nd Floor, Suite 200, Pittsburgh, PA 15219

END OF ADDENDUM NO. 2


Mr. Kim Detrick
Procurement Director/Contracting Officer


Date