

# Housing Authority of the City of Pittsburgh

Contracting Officer  
100 Ross Street  
2<sup>nd</sup> Floor Suite 200  
Pittsburgh, PA 15219  
(412) 456-5248  
Fax: (412) 456-5007  
[www.hacp.org](http://www.hacp.org)

**June 14, 2013**

## **Security Camera Maintenance RFP#200-12-13**

### **ADDENDUM NO.2**

This addendum issued June 14, 2013 becomes in its entirety a part of the Request for Proposals RFP#200-12-13 as is fully set forth herein:

**Item 1:** Q: May we have a copy of both sign in sheets from the pre-bid meeting?  
A: Please see Attachment A to this addendum, Pre-bid Sign-in Sheets

**Item 2:** Q: 3.7 Optional Pricing for software assurance does not have a corresponding line item on Attachment D for : Milestone Smart Client 7.0C Milestone Server 2008 Standard. Should we add these line items to Attachment D or will you create a new form?

A: Please see Attachment B to this addendum, Revised Attachment D to the scope of work.

**Item 3:** Q: What is the definition of response? If you cannot dial into a site, would your attempt to dial in count as a response or would you have to roll a truck to meet the minor, major or critical response time?

A: Vendor must begin to troubleshoot the problem and must notify the person who called in the outage that the vendor is actively working on the problem. Vendor may chose to notify HACP when they attempt remote access or may delay notification until a vendor staff member arrives on site. When the vendor notifies HACP that they are working on the problem the time to resolution clock begins to run.

**Item 4:** Q: Who would be qualified to call out a minor, major or critical issue from HACP?

A: A designated representative of the HACP Public Safety department. Or a member of the Management Information Services Department staff if no one in the Public Safety department is available.

**Item 5:** Q: If it is determined that we need to roll a truck to a site for a major or critical outage after hours, how will we contact that HACP representative and who will meet us on site?

A: Vendor will be given contact numbers for HACP staff who will be on call and responsible for coordinating access.

**Item 6:** Q: Your Milestone XProtect Corporate SUP licenses have expired and need to be renewed for the next year. Will this be added to Attachment D? This will be an annual expense.


A: This will be handled by HACP.

**Item 7:** Q: According to Samsung's parts list, all model numbers identified on Attachment A (installed equipment) are listed as "outdoor" cameras. That would make all 813 cameras listed in the RFP exterior cameras. How many of these are actually interior cameras?

A: Approximately 333 indoor cameras. The number may change slightly because final as-built documents have not been received from the firm installing the cameras.

**Item 8:** The proposal due date, time and location remain unchanged at June 21 2013 at 2:00 PM. at the HACP Procurement Dept., 100 Ross St. 2<sup>nd</sup> Floor, Suite 200, Pittsburgh, PA 15219.

**END OF ADDENDUM NO. 2**

  
Mr. Kim Detrick  
Procurement Director/Contracting Officer

June 19, 2013  
Date

Attachment A  
Pre-Bid Sign-in Sheets  
(RFP-200-12-13 Security Camera Maintenance)

# PRE-BID SIGN IN SHEET

Project Name and Number  
RFP#200-12-13 Security Camera Maintenance

Date Issued  
June 3, 2013

Due Date:  
June 21, 2013

Pre Bid Meeting  
June 13, 2013

Company Name	Company Address	Phone Number	Fax Number	E-Mail	Representative
HACP	100 Ross St Pgh 15219	412-456-5000 x8546	412-456-5007	Corinne.Lisetski@hac p.org	Corinne Lisetski
HACP	2305 Bedford Ave Pgh, PA 15219	412-456-5000 x1048 x1024	412-395-3970	Kira-Johnson@hmap.org	Kira Johnson
Aurid	1359 Barclay Blvd Ex #10 Grove, IL	847-404-9818	847-463-2068	Salemont@auridengroup.com	Sharon clermont
PSX Inc	2826 Penn Ave Pgh, Pa 15222	412-348-8326 (Cell) 412-338-4345 (office)	412-338-4341	Nick@ psxgroup.com	Nick 64818202
PSX Inc	2826 Penn Ave Pittsburgh PA 15222	412-951-7712	412-338-4347	matthew.allen@ psxgroup.com	Matthew Allen

# PRE-BID SIGN IN SHEET

Project Name and Number  
RFP#200-12-13 Security Camera Maintenance

Date Issued  
June 3, 2013

Due Date:  
June 21, 2013

Pre Bid Meeting  
June 13, 2013

Company Name	Company Address	Phone Number	Fax Number	E-Mail	Representative
UNICOM Technology Consultants	372 main ST Roslindale MA 01965	724 845 2740		For @unicomconsultants.com	For Wesley
HACP	200 Ross St. #805	412-456-5000 x8009	412-456-9204	Congre Dabhapong	Daniel Conge
HACP	200 Ross ST Suite 804	412-456-5100	412-456-5050	Wesley. Shrank@hacp.org	LARRY Shrank
HACP	200 Ross Street Suite 804	412 456 5000	412 456 5000	Joy. DeKam-milere@hacp.org	Joy Milere

# PRE-BID SIGN IN SHEET

Project Name and Number  
RFP#200-12-13 Security Camera Maintenance

Date Issued  
June 3, 2013

Due Date:  
June 21, 2013

Pre Bid Meeting  
June 13, 2013

Company Name	Company Address	Phone Number	Fax Number	EMail	Representative
JCI	117 Technology Drive, Pgh, PA 15275	412-639-0959		Sean.grim@jci.com	SEAN GRIMM
DES	600 MILLERS RD Pgh PA 15207	412-894-7015	412-531-4488	MILLERBECKER@DESCOMM.COM	MARK MILLERBECKER
DES	635 MILLERS RD Pgh, PA 15207	(412) 894-7024	(412) 531-4488	Vpacella@DESCOMM.COM	Vince PACELLA

Attachment B  
Revised Attachment D to the Scope of Work  
(RFP-200-12-13 Security Camera Maintenance)

**Total Cost. TO BE INCLUDED WITH FEE SHEET**

Base Bid - 3 Year Cost - In Scope Work \_\_\_\_\_  
 Year 4 optional 1 year extension \_\_\_\_\_  
 Year 5 optional 2nd year extension \_\_\_\_\_

Billed annually

Spare Parts Cost \_\_\_\_\_

**Total:** \_\_\_\_\_

<b>Optional Equipment Warranty</b>	<b>Cost</b>	<b>Term (Years)</b>
Samsung Camera's	_____	_____
APC UPS's	_____	_____

<b>Optional Software Assurance</b>	<b>Cost</b>	<b>Term (Years)</b>
Milestone Xprotect Corporate	_____	_____
Milestone Xprotect SmartWall	_____	_____
VMWare	_____	_____
Microsoft Server 2008 Standard	_____	_____



HACP - Service and Maintenance Contract  
 Attachment D to the Scope of work  
 Cost Sheet



Material	Cost each	Labor Each	Total
Alcatel OS6400-P24	_____	_____	_____
Alcatel OS6850E-P24	_____	_____	_____
Alcatel OS6850E-U24X	_____	_____	_____
Alcatel OS6850E-BPP	_____	_____	_____
Alcatel OS6850E-BP	_____	_____	_____
Alcatel OS6400-BP-P	_____	_____	_____
Alcatel SFP-GIG-SX	_____	_____	_____
Server comparable to Intransa CVA320-24TB-T2	_____	_____	_____
Workstation comparable to Intransa WS01	_____	_____	_____
Samsung Camera SNV-7080	_____	_____	_____
Samsung Camera SNP-3371TH	_____	_____	_____
Samsung Camera SNV-3120	_____	_____	_____
OT Systems ET411PH	_____	_____	_____
Altronix ALTV244175CB	_____	_____	_____
Altronix WPTV244175UL	_____	_____	_____
Altronix T2428100WP	_____	_____	_____

Additional Costs	Hourly Cost
Labor Type: _____	_____
Labor Type: _____	_____
Labor Type: _____	_____
Labor Type: _____	_____
Labor Type: _____	_____

Outage - Troubleshooting on-site not-to-exceed \_\_\_\_\_ an outage  
 Outage - Troubleshooting off-site not-to-exceed \_\_\_\_\_ an outage

Install 250' CAT-6 run through ex. Pathways \_\_\_\_\_

Markup/Overhead Percentage for out of scope work \_\_\_\_\_ %